


Muskrat Lake Watershed - Water Quality Monitoring Network

BC-01: Buttermilk Creek at Foresters Falls Road



SITE ID	DATE	TIME	PARAMETER	RESULT	UNIT
BC-01	2014-04-15	09:50	Total Nitrogen	0.93	mg/L
BC-01	2014-05-20	11:12	Total Nitrogen	0.47	mg/L
BC-01	2014-06-16	10:50	Total Nitrogen	0.46	mg/L
BC-01	2014-07-08	10:45	Total Nitrogen	0.81	mg/L
BC-01	2014-08-18	12:12	Total Nitrogen	0.46	mg/L
BC-01	2014-09-22	13:45	Total Nitrogen	0.37	mg/L
BC-01	2014-10-27	11:50	Total Nitrogen	0.41	mg/L
BC-01	2015-04-20	15:47	Total Nitrogen	0.55	mg/L
BC-01	2015-05-19	10:45	Total Nitrogen	0.42	mg/L
BC-01	2015-07-13	11:05	Total Nitrogen	0.29	mg/L
BC-01	2015-08-10	10:40	Total Nitrogen	0.35	mg/L
BC-01	2015-09-28	10:50	Total Nitrogen	0.32	mg/L
BC-01	2015-10-26	10:05	Total Nitrogen	0.24	mg/L
BC-01	2016-05-17	10:50	Total Nitrogen	0.36	mg/L
BC-01	2016-06-13	11:32	Total Nitrogen	0.27	mg/L
BC-01	2016-07-11	10:36	Total Nitrogen	0.73	mg/L
BC-01	2016-08-15	10:45	Total Nitrogen	0.48	mg/L
BC-01	2016-10-03	15:15	Total Nitrogen	0.29	mg/L
BC-01	2017-06-05	13:38	Total Nitrogen	0.43	mg/L

SITE ID	DATE	TIME	PARAMETER	RESULT	UNIT
BC-01	2017-07-10	12:00	Total Nitrogen	0.45	mg/L
BC-01	2017-08-15	11:24	Total Nitrogen	0.23	mg/L
BC-01	2017-09-18	11:50	Total Nitrogen	0.26	mg/L
BC-01	2017-10-30	14:05	Total Nitrogen	0.86	mg/L

Water samples are collected by Algonquin College (Pembroke) Environmental Technician co-op students and analyzed by the Ministry of Environment and Climate Change (MOECC) Laboratory Services Branch.